Hyderabad Cricket Association

Rajiv Gandhi Internatiol Cricket Stadium, Uppal

Supply and installation of mageable switches for spectarors count

BOQ - 05

SI No	Item Description	Qty	UMO	Make	Unit price	Amount
1	Supply and installation of CBS350- 24T-4G-IN CBS350 Managed 24 Port GE, 4X1G SFP	7	No's	CISCO		
2	Supply and installation of CON-SNT-CBS35GIN SNTC- 8X5XNBD CBS350 Managed 24 Port GE,4X1G SFP (Care pack 5 Years warranty)	7	No's	CISCO		
3	Supply and installation of GLC-LH-SMD= 1000 base- LX/LH SFP Transceiver module, MMF/SMF, 1310 DOM	28	No's	CISCO		
4	Supply and installation of SC LC Fibre single Mode Patch cord (3 MTR)	14	No's	Systamax/R &M/Comms cope		
GST 18 %						
Total amount						

(SUNEEL KANTE)
Chief Executive Officer

Rajiv Gandhi International Cricket Stadium Uppal, Hyd-500 039.